

MPX troubleshooting flowchart Dodge 2500/3500/4500/5500 2015 and above (Using snowplow 6 wires)

Front Installation


(module installed in the front)

Important Note:


- Use Power Probe III tool to troubleshoot the MPX system.
- https://www.youtube.com/watch?v=FuzfCOlA1Vw Link for Power Probe III tool instructions
- Update the modular box by updating tool (53707-N) if it was installed before 2017.
- See last page for more information on updating the modular box.



Controller Harness (Male Pins)




PIN #	COLOR	FUNCTION	
Α	RED	POS (+) to RING	
В	BLACK	GROUND	
C	BROWN	PUMP (SOLENOID)	
D	CAVITY PLUG	_	
Е	CAVITY PLUG	1	
Ŀ	CAVITY PLUG	1	
G	CAVITY PLUG	_	
Ι	CAVITY PLUG	1	
J	CAVITY PLUG	_	
K	WHITE	CONTROLLER SIGNAL	
L	GREEN	CONTROLLER SIGNAL	
М	RED/WHITE	POS (+) SWITCHED POWER (COMING FROM IGNITION SOURCE)	
		(COMING FROM IGNITION SOURCE)	







Plug A

Link for removing and reinstalling pins from female plug https://www.youtube.com/watch?v=VAm0plQlegs






PIN #	COLOR	FUNCTION	
Α	RED	POS (+) to RING	
В	BLACK	GROUND	
C	GREEN/YELLOW	TRIGGER	
О	YELLÓW/RED	DRIVERS SIDE HIGH BEAM	
ш	GREEN/RED	DRIVERS SIDE LOW BEAM	
F	WHITE/RED	COMMON	
G	VIOLET	DRIVERS SIDE TURN	
Ι	PINK	CURB SIDE TURN	
7	GREY	RUN/PARK	
K	CAVITY PLUG	_	
١	CAVITY PLUG	•	
2	CAVITY PLUG	-	



PIN FACE (FRONT VIEW)








Plug B

Link for removing and reinstalling pins from male plug https://www.youtube.com/watch?v=BB6tE096HkQ

Page 2







PIN FACE (FRONT VIEW)

Plug view of Truck Light Harness— Front Installation (Dodge 6 wires) Connect Pin A and Pin C

PIN #	COLOR	FUNCTION	
Α	RED	POS (+) to RING	
В	BLACK	GROUND	
С	C GREEN/YELLOW TRIGGER		
D	YELLÓW/RED	DRIVERS SIDE HIGH BEAM	
E	GREEN/RED	DRIVERS SIDE LOW BEAM	
F	WHITE/RED	COMMON	
G	VIOLET	DRIVERS SIDE TURN	
Н	PINK	CURB SIDE TURN	
J	GREY	RUN/PARK	
K	CAVITY PLUG	_	
L	CAVITY PLUG	_	
M	CAVITY PLUG	_	







Unclip the fuse box



Lift the box and find 6 wires, attach them to the harness as shown



	Vehicle Harness		Light Adapter Harness	Function
Connect	Black/Lt. Blue	То	Blue	High Beam
Connect	Black/Lt. Green	То	Lt. Green	Low Beam
Connect	White/Brown	То	White	Park
Connect	White/Violet	То	Violet	DS Turn
Connect	Violet/Brown	То	Pink	CS Turn
Connect	Black/Violet	То	Green/Yellow	Snowplow Enable wire



LB Relay

Park light Relay

Under the vehicle's hood

HB (Blue)

LB (Lt.Green)

In front of vehicle's grille

DS- Driver Side

LEGEND

CS - Curb Side

HB - High Beam

LB - Low Beam


HB Relay



Click on the link below to refer to the specific troubleshooting step:

- Marker/Position light on one side of plow headlights is not working.
- Marker/Position lights on both the sides of plow headlights are not working
- High beam / Low beam on one side of the plow headlights is not working.
- High beam on both the sides of plow headlights are not working.
- Low beam on both the sides of plow headlights are not working.
- Turn Signal on Driver side of the plow headlight is not working.
- Turn Signal on Curb side of the plow headlight is not working.
- Plow does not operate and lights on the plow are not working.
- Plow does not operate.
- Lights do not transfer to the plow.
- Individual functions on the plow are not working.
- Controller lights keep on changing.






Click on the link https://www.youtube.com/watch?v=NwhY_zgbx6A to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=k-EJpEOH0Mc to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=c4yPVrKAKQo to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=uyTPPK0zJSE to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=vn8NaWM6WAw to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=3svwMLNWIPI to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI

Link for 800086 headlights: https://www.youtube.com/watch?v=sA7AxDIYgwc






Click on the link https://www.youtube.com/watch?v=hC37CmltS6Y to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI


Link for 800086 headlights: https://www.youtube.com/watch?v=sA7AxDIYgwc






Click on the link https://www.youtube.com/watch?v=7Xb6IqrcroE to watch the video of this specific troubleshooting step.





Click on the link https://www.youtube.com/watch?v=VFVqe-yPWjU&feature=youtu.be to watch the video of this specific troubleshooting step.





Connect Pin "A" to "C" on Plug "B" (refer to Page 3). After connecting, check the following on plug "B" (refer to Page 2) in the front of the truck:

- -12 V must be present on pin "D" when High Beam is turned on the truck.
- -12 V must be present on pin "E" when Low Beam is turned on the truck. If voltage is not present, check the wire connections and relays condition on Dodge 6 wires, make sure they are connected accordingly (refer to Page 4 to see proper connection). If necessary repair/replace the relays or even light adapter harness. Problem solved?

Replace the modular box or lift frame harness if needed.


Restart truck's ignition after every step of troubleshooting

Click on the link https://www.youtube.com/watch?v=vn8NaWM6WAw to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q


Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI





Click on the link https://www.youtube.com/watch?v=K1ERrFWnUw0 to watch the video of this specific troubleshooting step.






Click on the link https://www.youtube.com/watch?v=gKqEarX4FrQ to watch the video of this specific troubleshooting step.




Connectors alignment for the MPX system





Tool for updating MPX module box (53707-N)



Check the link below to see step by step procedure on how to update the module box on your truck:

https://www.youtube.com/watch?v=nGSTAm8hZ9Y